

Compatibility Matrix | V-Mount

antonbauer.com/chargercompatibility

Batteries

Chargers

Legacy products

	DIONIC XT 90	DIONIC XT 150	Titon 90	Titon 150	Titon 240	Titon SL 90	Titon SL 150	Titon Micro 45	Titon Micro 90	Titon Micro 150	GO90	CINE V90	CINE V150	Digital V90	Digital V150	Digital V190	Titon Base*
Anton/Bauer LP2 Firmware Rev: 12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Anton/Bauer LP4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Anton/Bauer Performance DUAL Firmware: 10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Anton/Bauer Performance QUAD Firmware: 10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Anton/Bauer 26V Firmware Rev: 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Anton/Bauer VM2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Anton/Bauer VM4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Bebob S4 Micro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Bebob S1 Micro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	-
Bebob VAS2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Blueshape D-TAP	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Blueshape CVTR2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Century Optronic CO-2044	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
CORE P-Tap PB70C15US	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓
CORE GPM-X2S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
CORE FLEET Q4i	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
CORE FLEET D2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
CORE FLEET Q4-Micro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
CORE FLEET Q4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Frezzi FLC-2V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	

For charger firmware updates & to schedule repairs please contact your nearest service center: antonbauer.com/servicecenter
Charger must be using the up to latest firmware

Legend

- ✓ Tested, compatible
- ✓¹ Tested, compatible but LCD shows 97%
- ✗ Not compatible
- Not tested
- ~ Does not fully charge
- Incompatible mount type

*Titon Base charges via a P-tap charger which plugs into a wall socket.

Compatibility Matrix | V-Mount

antonbauer.com/chargercompatibility

Batteries

Legacy products

Chargers

	DIONIC XT 90	DIONIC XT 150	Titon 90	Titon 150	Titon 240	Titon SL 90	Titon SL 150	Titon Micro 45	Titon Micro 90	GO90	CINE V90	CINE V150	Digital V90	Digital V150	Digital V190	Titon Base*
Hawk Woods VL-MX2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Hawk Woods VL-MX4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Hawk Woods VL2X2 2 Channel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Hawk Woods VL4X44 Channel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Hawk Woods 2X2 Compact - Channel	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Hawk Woods 8 way 8 Channel Charger	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
IDX D-Tap VL-DT1	✗	✗	✗	✗	✗	✗	✗	✗	✗	✗	✗	✗	✗	✗	✗	✗
IDX VL-4Se	✓	✓	✓	-	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
IDX VL-4Si (NEW)	-	-	-	-	-	-	-	-	-	-	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
IDX VL-4Si (OLD)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
IDX VL-2Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
IDX VL-2X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
PAGLink PL16	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
PAGLink Cube 9708	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
Pro - X GP2LSJ	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
RED CVTR2	-	-	-	✓	✓	✓	✓	✗	✗	✗	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
SWIT SC-302S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
SWIT S-3812S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
SWIT S-3822S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
SONY BC-L160	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
SONY BC-L100	~	~	~	~	~	~	~	~	~	~	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
SONY BC-L70	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	
SHAPE G018-20190917	✗	✗	✗	✗	✗	✗	✗	✓	✓	✓	✗	✗	✗	✗	✗	
Watson P-Tap C-SPT	-	-	-	-	✓	-	-	-	-	-	✓ ¹	-	✓ ¹	✓ ¹	✓ ¹	✓

For charger firmware updates & to schedule repairs please contact your nearest service center: antonbauer.com/servicecenter
Charger must be using the up to latest firmware

Legend

- ✓ Tested, compatible
- ✗ Not compatible
- ~ Does not fully charge
- Incompatible mount type
- ✓¹ Tested, compatible but LCD shows 97%
- Not tested

*Titon Base charges via a P-tap charger which plugs into a wall socket.